

April 22, 2025

To: CNH Industrial Dealers

Attn: Parts Managers

No.: Dealer Quality Alert – QM00000064093

Subject: Dealer Quality Alert Notice – 87601413 Reman Alternator

Criteria for Alert: 87601413 Reman Alternator should have a serial number starting with 24xxxxxxx or 25xxxxxxx. Incorrect Reman alternators had a serial number starting before 24xxxxxxx (example 23xxxxxxx, 22xxxxxxx). Specific date codes of affected parts were not provided. Inspect based on serial number.

File a claim for all 87601413 Reman Alternators that have serial numbers before 24xxxxxxx by May 22, 2025.

Please submit a service parts claim for the non-conforming parts found during your inspection. The following process must be followed when submitting the service parts claim:

- 1) Only parts that have <u>not been installed</u> are to be returned or scrapped. Dealers are NOT to remove parts from equipment and return or scrap them on this alert.
- 2) Submit all claims in CSPS.

20 Babale

- 3) Use the following claim submission message:
 - a) <u>Dealer Alert (QM00000064093 87601413 Reman Alternators)</u>
- 4) Use Reason Code R for claim submission.
- 5) Ship parts to be returned per instruction provided on the Return Authorization Notice (RAN) when it is received.
- 6) Returned parts are to be **packaged separately**. Do not pack with any other returns.
- 7) Returns must be shipped by the date indicated on the RAN. Parts received at the facing depot outside of the allowable return date window MAY BE rejected.

Edward Bobski – Supplier Quality Manager, CNH Reman, Springfield, Mo.

General Business

